



Piper Aircraft, Inc.
2926 Piper Drive
Vero Beach, FL, U.S.A. 32960

SERVICE SPARES LETTER

NO. 448A

Date: August 14, 2023

Service Spares Letter (SSL) 448A supersedes SSL 448 in its entirety.

SUBJECT: MAINTENANCE, SERVICE, AND PARTS PUBLICATIONS DISTRIBUTION

MODELS AFFECTED: ALL
SERIAL NUMBERS AFFECTED: ALL

PURPOSE: To announce changes to the distribution of Maintenance/Service Manuals, Parts Catalogs, and Service Publications via subscription.

SUMMARY: ATP Aviation Hub, Piper's exclusive distributor for all Maintenance/Service Manuals, Parts Catalogs, and Service Publications, is now Veryon Technical Publications. See <https://www.veryon.com/> for details and to order. Or, contact a product specialist at 1-800-747-4560 or via email at customersupport@veryon.com.

NOTE: Subscribers to our free Piper Publication Notification service will continue to receive emails directly from Piper when new service publications are issued. Additionally, recent service publications will continue to be available at <https://www.piper.com/>.

NOTE: For Piper Maintenance/Service Manuals, Parts Catalogs, and Service Publications by subscription, contact:

Veryon
101 South Hill Drive
Brisbane, California 94005
U.S.A.
Worldwide: 1-800-747-4560
Email: customersupport@veryon.com
<http://www.veryon.com/>